

From: Owen Chaplin <ochaplin@gorrillpalmer.com>
Sent: Monday, December 11, 2017 1:39 PM
To: Amanda L. Lessard
Cc: Will Haskell
Subject: Valley View - Status
Attachments: IMG_6087.JPG; IMG_6088.JPG

Hi Amanda,

I received a call from Chris Duchaine inquiring about Valley View. What's the status of this project – is the Town waiting on something from us?

My understanding is the only remaining items that needed to be addressed were cleaning the catch basins and mowing the underdrain soil filters. These items have been addressed and appear complete. However, since the underdrain soil filters were mowed, standing water is visible in underdrain soil filter #2 and it doesn't appear to be draining properly. The cause of the ponding is unknown but it's fair to assume that the constant sediment runoff/accumulation in the road has clogged the system. Is this something that could be addressed in the DEP 5 Year Recertification, or should DDI address this issue now?

Give me a call if you have any questions.

Thank you,
Owen

Owen C. Chaplin | Project Engineer



707 Sable Oaks Drive, Suite 30 | South Portland, ME 04106
207.772.2515 x232 (office) | 207.400.7113 (mobile)
www.gorrillpalmer.com

The information transmitted is intended only for the person or entity to which it is addressed and may contain confidential and/or privileged material. Any review, retransmission, dissemination or other use of, or taking of any action in reliance upon, this information by persons or entities other than the intended recipient is prohibited. If you have received this email in error, please contact the sender and delete the material from any computer.

