

Town of Windham's
Inspections Summary - By Inspection Type
 Month of October, 2014

Inspection Type	Passed	% Passed	Partial	% Partial	Failed	% Failed	Total	Inspection Trip Time	Inspection Trip Mileage
Assessor Inspection	14	100.00%	0	0.00%	0	0.00%	14	00h 00m	0
Building Final	11	91.67%	1	8.33%	0	0.00%	12	00h 48m	5
Building Footing	18	100.00%	0	0.00%	0	0.00%	18	00h 00m	0
Building Foundation Backfill	13	92.86%	1	7.14%	0	0.00%	14	00h 35m	18
Building Foundation Rebar	11	100.00%	0	0.00%	0	0.00%	11	00h 12m	8
Building Framing	15	62.50%	9	37.50%	0	0.00%	24	03h 28m	48
Building Insulation	8	88.89%	1	11.11%	0	0.00%	9	01h 33m	29
Certificate of Occupancy	20	80.00%	5	20.00%	0	0.00%	25	00h 28m	5
Chimney Inspection	1	100.00%	0	0.00%	0	0.00%	1	00h 48m	8
Electrical Final	5	83.33%	1	16.67%	0	0.00%	6	00h 00m	0
Electrical Permanent Service	25	100.00%	0	0.00%	0	0.00%	25	03h 27m	37
Electrical Rough-In	17	80.95%	4	19.05%	0	0.00%	21	00h 49m	17
Horizon Inspection	15	100.00%	0	0.00%	0	0.00%	15	00h 00m	0
In-Office Appointment	45	97.83%	1	2.17%	0	0.00%	46	06h 49m	0
On Site Visit	1	100.00%	0	0.00%	0	0.00%	1	00h 00m	0
Plumbing Final	5	83.33%	1	16.67%	0	0.00%	6	00h 00m	0
Plumbing Rough-In	13	68.42%	6	31.58%	0	0.00%	19	00h 00m	0
Plumbing Sub Slab	1	100.00%	0	0.00%	0	0.00%	1	00h 00m	0
Septic Field Final	19	95.00%	1	5.00%	0	0.00%	20	01h 21m	13
Septic Tank	3	100.00%	0	0.00%	0	0.00%	3	00h 00m	0
Site Visit	7	100.00%	0	0.00%	0	0.00%	7	01h 08m	5
Site Visit Follow up	1	100.00%	0	0.00%	0	0.00%	1	00h 00m	0
Totals	268	89.63%	31	10.37%	0	0.00%	299	21h 26m	193